

We provide software updates to improve your experience using our devices.

This update covers bug fixes and performance improvements. Sync Module 2 firmware version is being updated from version 16.0.8 to 16.0.10. The size of this update is 429KB. Impact on Storage, RAM, and battery life is not applicable.